


## PRESSURE MAPPING, FORCE MEASUREMENT, AND TACTILE SENSORS



General Dimensions			Sensing Region Dimensions						Summary			
Overall Length <i>L</i>	Overall Width <i>W</i>	Tab Length <i>A</i>	Matrix Width <i>MW</i>	Matrix Height <i>MH</i>	Columns			Rows			Total No. of Sensels	Sensel Spatial Resolution
					<i>CW</i>	Pitch <i>CS</i>	<i>Qty.</i>	<i>RW</i>	Pitch <i>RS</i>	<i>Qty.</i>		
(mm)	(mm)	(mm)	(mm)	(mm)	(mm)	(mm)		(mm)	(mm)			(sensel per sq-cm)
406.4	104.1	330.2	24.8	40.0	1.1	1.9	13	1.1	1.9	21	273	27.6
(in)	(in)	(in)	(in)	(in)	(in)	(in)		(in)	(in)			(sensel per sq-in)
16.00	4.10	13.00	0.98	1.58	0.045	0.075	13	0.045	0.075	21	273	177.8

Pressure Ranges	
kPa	3,448
psi	500