


## PRESSURE MAPPING, FORCE MEASUREMENT, AND TACTILE SENSORS



General Dimensions					Sensing Region Dimensions						Summary	
Overall Length <i>L</i>	Overall Width <i>W</i>	Tab Length <i>A</i>	Matrix Width <i>MW</i>	Matrix Height <i>MH</i>	Columns			Rows			Total No. of Sensels	Sensel Spatial Resolution
					<i>CW</i>	<i>CS</i>	<i>Qty.</i>	<i>RW</i>	<i>RS</i>	<i>Qty.</i>		
(mm)	(mm)	(mm)	(mm)	(mm)	(mm)	(mm)		(mm)	(mm)			(sensel per sq-cm)
565.2	337.8	411.2	307.3	33.0	1.8	7.0	44	0.4	0.6	52	2,288	22.5
(in)	(in)	(in)	(in)	(in)	(in)	(in)		(in)	(in)			(sensel per sq-in)
22.25	13.30	16.19	12.10	1.30	0.070	0.275	44	0.015	0.025	52	2,288	145.5

### Pressure Ranges

kPa	68,950
psi	10,000