



Description	Initiator	Date
Changed Tap hole size on customer holes from M12 to M10. Updated Notes. itle Block.	CF	7/19/2010
Eliminated limit dim on 10mm dowel	LJH	1/24/2017